Work Order ID July 5, 2010 10:33:06	1				*						Page 1	
tem ID: D3916 Revision ID: tem Name: Light R			Accept				Se	etup S	tart Stop			-
Start Date: 7/05/10 Required Date: 7/09/10 Reference:	Start Qty: 9.00	#	. 1	Cust Item I Customer:	D:							
	ess Plan:	Date:/ 7/C			ate:		R		tart Stop			
Sequence ID/ Work Center ID	Operation Description	<del></del>	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty		eject lumber	Insp. Stamp	
Draw Nbr	Revision Nbr											_
D3916	Α ,											
00                                - Large Fab	Memo		0.00				9					
arge Fab	1- Cut tube 2- Bend tul *** Make	e 50" be with manuel pipe bender line at 9.00" annd use jig fo cess tube material to finish	as per DT9566 or other line***	SAD			ι.				Pho	->
10  QC  Quality Control	QC5- Inspect part comp	oleteness to step on W/O	0.00	olustia	· .		(F)				and an artificial section .	
		Stock Location:	0.00 SA	40° -07'20			(a)					
Packaging Packaging	Memo		0.00	-O + ~								

## **Dart Aerospace Ltd**

	WORK ORDER CHANGES											
STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector						
	STEP					STEP PROCEDURE CHANGE By Date Qty Chief Eng /						

Part No: 1035/6-5 PAR #: Fault Category: Lage Fob NCR: Ves No DQA: Date: 1007/20

Resolution: Scrap Disposition: Scrap. QA: N/C Closed: Date: 1007/20

Verification	Approval	Approval
Section C	Chief Eng	QC Inspecto
	8	
8	ODD	
10/07/9		15/2/
		<del> </del>
	rolorla	10/07/9

NOTE: Date & initial all entries

Work Order ID  July 5, 2010 10:33:06										Page 2
Item ID: D3916 Revision ID: Item Name: Light R			Accept				s s	Setup Sta	1 1001110	
Start Date: 7/05/19 Required Date: 7/09/19 Reference:	0 Start Qty: 9.00			Cust Item I Customer:	D:				1.22	
	ess Plan:	Date:	Tooling: SPC (Y/N):		ate:	-	F		op	
Sequence ID/ Work Center ID 130	Operation Description QC21- Final Inspection	1 - Work Order Release	Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	
QC Quality Control	Memo		0.00						M	- Jiou C -7-20

.....

2

. .

## **Dart Aerospace Ltd**

Duit AU	oopaoc .					•			
W/O:			WC	ORK ORDER CHANG	SES				
DATE STEP		PRO	OCEDURE CHA	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
								• .	
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DG	A:	_ Date: _	
	Res	solution:	Dispositio	n:	QA: N/C (	Closed: _		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	OTED	Description of NC		· · · · · · · · · · · · · · · · · · ·	tion B	Verif	ication	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sec	tion C	Chief Eng	QC Inspector
	,								
			ī						

NOTE: Date & initial all entries

July 5, 2010 10:33:05 AM

Work Order ID: 60321

Parent Item:

D3916-5

Parent Item Name: Light Rib



**Start Date:** 7/05/10

Required Date: 7/09/10

Start Qty: 9.00

Required Qty: 9.00

Comments:

IPP RevA: new issue DD 09.11.23 verified by:EC as per dwg revA 10.03.15 verified by:EC


IPP Rev:B

	s per angrenir ro		,										
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304TS0.500W.049		Purchased	No			100	f	317.0184	4.166	39.46737 SAD	V	0-0-	- 10
quare ruomg	ŀ			Location		Loc C	<u>Oty</u>	Loc Code					
1	ļ			MAT		309.9221	158						
					114004		0		_				
	ļ				114426	9.2	647		_				
					114807	44.1709	158		-3				
	1				115034	256.4	865			39.467	.4		
	1			MAT018	ì	4.4	738		_		•		
1	1				114004		0.5						
f, •	1			r,	114161	3.9	738		ε.				
				WA		2.62	251					•	
	,				114724	2.62			_				

## **Dart Aerospace Ltd**

Dail Ac	ospace	Liu							
W/O:			WC	RK ORDER CHANG	GES				
DATE	STEP	PRO	OCEDURE CHA	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector	
									<u> </u>
			***************************************						
		4.01	-						
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _	
	R	esolution:	Dispositio	າ:	QA: N/C CI	osed:		Date: _	
NCR:		1	WORK ORDI	ER NON-CONFORM	ANCE (NCF	l)			
DATE	OTED	Description of NC	<u> </u>		tion B	Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspecto
				•					
	_								
1									

NOTE: Date & initial all entries




-D3916-1 RIB D3759-1-BUSHING 7 PL D3916-041 RIB ASSY


PELEASED 2010 -03- 1 2

NOTES:
1) MATERIAL: N/A
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: N/A
6) IDENTIFICATION: NONE
7) WEIGHT -041: 1.84 lbs;
8) WELD PER DART QSI 004

w10' 60321

DESIGN	AJS	DART AEROSPACE	LTD
DRAWN	JPH	HAWKESBURY, ONTARIO, CAN	ADA
CHECKED	9	DRAWING NO.	REV. A
MFG, APPR.	E	D3916	SHEET 2 OF 4
APPROVED	MAL	TITLE	SCALE
DE APPR.	-	☐ RIB ASSY, 350 BASKET	NTS
DATE 10.0	3.04	COPYRIGHT © 2010 BY DART AEROSPA THIS COCUMENT IS PROVATE AND CONFEDENTIAL AND IS SUPPLIED ON THE EXP HOT TO BE USED FOR ANY PLEASONS FROM DARE ASSENTIATED TO ANY WIGHT IN MERISSON FROM DARE ASSENTIACE TO	RESS CONDITION THAT IT IS OTHER PERSON WITHOUT





DELEASED 2010 -03- 1 2

NOTES:
1) MATERIAL: AISI 304/316 STAINLESS STEEL SQUARE TUBE, 0.50 X 0.50 X 0.049 WALL REF DART SPEC. M304TS0.500W.049
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: NIA |
7) WEIGHT: 1.07 Ibs
9) TUBE FLAT LENGTH 49.5 REF

w10.60321

DESIGN	AJS	DART AEROSPACE	DART AEROSPACE LTD						
DRAWN	JPH	HAWKESBURY, ONTARIO, CAN	IADA						
CHECKED	9	DRAWING NO.	REV. A						
MFG. APPR.	3	D3916	SHEET 4 OF 4						
APPROVED	MA	TITLE	SCALE						
DE APPR.	-4-	RIB ASSY, 350 BASKET	NTS						
DATE 10.0	3.04	COPYRIGHT © 2010 BY DART AEROSP/ thes document is prevate and confidently, with is supplied on the EX HOT TO BE USED FOR ANY PURPORE OR COPIED OR COMMUNICATED TO M	RESS CONDITION THAT IT IS OTHER PERSON WITHOUT						